

id 6024

Pram

[50,8 m kran pram](#)

| | |
|-------------------------|--------------------------------|
| Skibs-id | 6024 |
| Kategori | Pram |
| Byggeår | 2020 |
| Pris | \$3,200,000 |
| Skibets tilføjelsesdato | 2022-05-30 |
| Tilføjet af | Vlad (Varamar) |

Skibets dimensioner

| | |
|------------------------|-------|
| Samlet længde (LOA), m | 50.8 |
| Dybde, m | 3.6 |
| Fartøjs dybgang, m | 1.414 |

Yderligere Information

| | |
|-------------|-----------------|
| Hovedmotor | 1000hp + 1000hp |
| Selvkørende | |

| | |
|----------------|--|
| Lignende skibe | Vis lignende skibe |
| Forespørgsler | Matchende indkøbsanmodninger |
| e-mail | Send e-mail |



FQ5008 吊机的500吨是定期维护的，保养是定期加注润滑油可以，同时又每半个月加一次，其余地方半个月加一次。

The FQ5008 crane (50T) is easy to maintain. Maintenance is the need to fill lubricating oil all can be regularly, showing bearing filling once a month, the rest of the 6 months filling once.

其余部分有定期保养的，配件需要备一些备用件，液压油定期换，然后电液的一些接触器点什么的，坏了就换，不坏的定期更换的，吊机坏了，人员可以外派维修。

主要是换油如下。（根据使用状况为2到3年配件用量）

There is no need to maintain the rest, spare parts need to prepare part of the brake pad, hydraulic actuator, and then some electrical contact contacts, broken to replace, there is no regular replacement, if the crane has problem which cannot be fixed, personnel can be dispatched to repair.

The main wearing parts are as follows (2 to 3 years of spare parts consumption according to the use)

| 名称 | 数量 | 单价 | 总价 |
|-----------------|----|------|-------|
| LC1-F225A 4P接触器 | 1 | 3702 | 3702 |
| LC1-F225A 4P线圈 | 1 | 570 | 570 |
| LC1-F225A 4P主触点 | 1 | 1450 | 1450 |
| LC1-D09接触器 | 2 | 55 | 110 |
| KKM2LBP7中阻 | 40 | 20 | 800 |
| LC1-D820MTC接触器 | 1 | 7870 | 7870 |
| 3RT3075 400A接触器 | 1 | 2570 | 2570 |
| 3RT3075 400A线圈 | 1 | 350 | 350 |
| 3RT3075 400A主触点 | 1 | 1124 | 1124 |
| 主付机刹车油泵 | 2 | 2780 | 5560 |
| 主付机刹车片 | 16 | 300 | 4800 |
| 变幅方向节 | 1 | 2200 | 2200 |
| 主付机吊钩 | 2 | 160 | 320 |
| 转向刹车皮 | 8 | 165 | 1320 |
| 总价 | | | 33076 |

以上价格为人民币价格，总计 33076 元（美元的 5250 美金），（根据使用状况为2到3年配件用量） The above price is RMB 33,076 yuan (or 5,250) in total. (2 to 3 years of spare parts consumption depending on usage)

